

Magi No.

DOE __yes __no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

street & number west side of Clark Road, .1 mile north of Sandy Hook Road not for publicationcity, town Sandy Hook _____ vicinity of _____ congressional district sixthstate Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military
			<input type="checkbox"/> museum
			<input type="checkbox"/> park
			<input checked="" type="checkbox"/> private residence
			<input type="checkbox"/> religious
			<input type="checkbox"/> scientific
			<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

m. 87 p. 136

street & number

telephone no.:

city, town

state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstownstate Maryland

6. Representation in Existing Historical Surveys

title

date

____ federal ____ state ____ county ____ local

depository for survey records

city, town

state

7. Description

Survey No. WA-III - 113

Condition

☐ excellent
☒ good
☐ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story, two-bay by two-bay structure with one-story additions on the north and south facades. The east facade is the main facade of the structure although it appears that originally the south gable end has the main facade. The east facade is asymmetrically arranged with the one-story southern addition containing a window and a door, the two-story main section containing a door and a window, and the one-story north addition containing a row of four connected windows. The second story contains a two-over-two sash window in the northernmost bay. The structure is constructed of frame and covered in a asphalt siding. There is a one-story porch running the three southernmost bays. The structure appears to date from the early 20th century.

The property is located on the west side of Clark Road, approximately .1 mile north of Sandy Hook Road, in Sandy Hook. The structure sits slightly back from the road. The main facade faces east.

The two-story structure is constructed of frame and covered in a asphalt shingle. The main facade is asymmetrically arranged. It has a one-story porch running along the two bays of the southern addition and one bay of the main section. The porch has a shed roof covered in sheet metal and is supported by square posts with panelled railing. The southern addition has a entrance and a one-over-one sash window. The main section has a entrance and a two-over-two sash window. There is a single two-over-two sash window on the second story. The northern addition has a shed roof and a row of four connected windows. On the north gable end is an interior-end brick chimney that rises from the exterior of the main section above the first story. The main section has a boxed cornice. The roof is covered in sheet metal.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-III - 113

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook Survey District.

Survey No. JA-III-113

PS-2746

FREDERICK & INGTON

HARPERS FERRY, VA-MD-W VA
QUADRANGLE

USGS 7.5 minute map
1:24 000
1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST

767

768

5462 / NW (KEEDYSVILLE)

769





1. WA-III-113
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. ~~South~~^{East} elev. (camera facing ~~north~~)
7. 1/1 ~~west~~